



# **MK 66 ROCKET MOTOR/HELICOPTER COMPATIBILITY PROGRAM**

**27 MARCH 2003**

**ERIC HAWLEY**

**Contact Information**

**Ph: (301) 744-1822**

**Fax: (301) 744-4410**

**[hawleyej@ih.navy.mil](mailto:hawleyej@ih.navy.mil)**

**INDIAN HEAD DIVISION  
NAVAL SURFACE  
WARFARE CENTER  
INDIAN HEAD, MD**

## Helicopter Engine Compatibility Background

- **Problem description:**
  - AH-1F downed with fatalities in 1988 while firing MK 66 Rocket Motors
  - Army investigation concluded that the accident was caused by engine ingestion of high-temperature, oxygen-depleted rocket exhaust gasses
    - AH-1 physical mod implemented (air scoop)



## Helicopter Engine Compatibility Background

- **AH-64 testing identifies rocket exhaust ingestion into engines still a problem**
  - Causes engine torque splits and torque fluctuations (surges)
  - Physical mod to aircraft considered not practical
  - Firing restrictions in effect





## Helicopter Engine Compatibility Background


- High temperature oxygen depleted rocket exhaust caused by secondary combustion
- Secondary combustion (afterburning) occurs when CO and H<sub>2</sub> in the exhaust react with oxygen in atmosphere

### Current MK 66 exhaust components

Combustion Component	Exit Composition (mole fraction)
CO <sub>2</sub>	0.1898
CO	0.33007
H <sub>2</sub> O	0.18146
H <sub>2</sub>	0.17295
N <sub>2</sub>	0.12218
Pb	0.00177
Cu	0.00177



# MK 66 Rocket Motor Background



**MK 66 MOD 4 ROCKET MOTOR**

## Helicopter Engine Compatibility Approach

- **Secondary combustion can be suppressed by introducing more potassium sulfate ( $K_2SO_4$ ) into motor exhaust**
  - **Mod 0-4 Salt Rod addresses rocket exhaust ingestion issue in fixed wing aircraft**
  - **Helicopter ingestion situation is the same**
    - **Ingestion timeline is different**
    - **Existing salt rod consumed in 6 feet of motion**
    - **Helicopters need salt rod effect through rotor downwash**
    - **Army Aviation Engineering specifies 30 feet as necessary**




## Salt Rod Modification

- There is a linear relationship between salt volume and duration of afterburning suppression
- Amount and shape of salt rod modified to increase effectiveness for 30 feet
- Enlarged salt rod contains ~ 3x more  $K_2SO_4$

MOD 4

Modified



- $K_2SO_4$  reactions

- Afterburning reaction:



Atmospheric oxygen


- Reaction with  $K_2SO_4$ :



- $K_2SO_4$  provides oxygen to the exhaust, which delays the overall reaction of the exhaust fuels ( $H_2$  and  $CO$ ) with the atmospheric oxygen ( $O_2$ )




# Static Fire Test



## Static Fire Test Results


- Motor exhaust temperature found to be more than 20% lower than current MK 66 motors at 77 F and 150 F




## Ground Launch Results

- Suppressed flight distance >30 ft average

**MK 66 MOD 3 ROCKET MOTOR (150 F)**




**HELICOPTER COMPATIBILITY ROCKET MOTOR (150 F)**




# Ground Launch Results

- Ground launch thermal data

MK 66 MOD 3 ROCKET MOTOR (150 F)



HELICOPTER COMPATIBILITY ROCKET MOTOR (150 F)



## Air Launch Verification

- **Air launch test on an instrumented AH-64A with MK 66 motors w/ enlarged salt rod conducted in 1998**
- **Test conditions**
  - **10 knot wind restrictions**
  - **Altitude was 150 ft**
  - **Air temperature was in upper 70s, 70-80% RH**
  - **Test pass/fail criteria:**
    - **Torque split exceeds 15%,**
    - **Main engine torque fluctuations of  $\pm 15\%$ ,**
    - **Tail rotor torque fluctuations of  $\pm 500$  ft-lbs**




# Air Launch Results

- All engine surge conditions eliminated except one
  - Hover: All surge conditions eliminated
  - 40 kts forward flight: All conditions but one eliminated

CONDITION	LEFT OUTBOARD		LEFT INBOARD		RIGHT INBOARD		RIGHT OUTBOARD		MK 66 MOD 3	HELICOPTER COMP
	ROCKET DENSITY	ROCKETS FIRED	ROCKET DENSITY	ROCKETS FIRED	ROCKET DENSITY	ROCKETS FIRED	ROCKET DENSITY	ROCKETS FIRED	ROCKET MOTOR	ROCKET MOTOR
HOVER	10	2								
	8	8								
	12	12								
	19	19								
	19	19					19	19		
			14	2					1	TESTED TWICE
			12	4					1	TESTED TWICE
			8	8						
					19	2				
					17	2				
				15	2					
40 KTAS FORWARD	16	4								
	12	12								
	19	19								
			19	2/1					1	1, 1 (NOTE 1)
			17	2/1					1	1 (NOTE 2)
			15	2						
			2	2						
					19	2			1	TESTED TWICE
					17	2			1	TESTED TWICE
					15	2			1	TESTED TWICE
	12	4					12	4	1	TESTED TWICE
	8	8					8	8	5	

## Air Launch Results (cont.)


- **Worst condition: 40 kts forward flight, one or two rockets fired from left inboard launcher**





## Internal Pressure Concerns


- **Enlarged salt rod causes ignition pressure spikes**
  - Enlarged salt rod known to increase pressure, and therefore thrust during ~ 0.10 second of burn
  - Measured thrust values near MK 66 specification limit of 2100 lbf





## Pressure Differential Test


- Thrust requirement derived from internal forward end measured pressures
- Aft end known to be weakest point on motor (lockwire joint)
- Efforts made to measure pressure at aft end



Lockwire joint


## Pressure Differential Test

- **Pressure differential test performed at Indian Head in June 2002**
  - Previous analysis predicted a 350 - 500 psi drop at 150°F
  - Aft pressures measured ~400 psi lower than forward end during first 0.10 seconds at 150°F



## Pressure Differential Test Results

- **Thrust limit redefined based on aft end pressures**
  - **Recommended a new thrust limit of 2500 lbf for the first 0.10 seconds of burn**
    - **Maintains motor tube factor of safety of 1.5**
    - **Verified by analysis and historical data**



## Future Work

- **Enlarged salt rod design will be incorporated into the MK 66 MOD 6**
- **Qualification of MOD 6 scheduled to begin in this spring**
  - **Qualification includes:**
    - **Environmental Tests**
    - **Ground Launch**
    - **Air Launch**
- **Due to enter production midway through FY04**



## Questions

### Contact Information

**ERIC HAWLEY**

**Ph: (301) 744-1822**

**Fax: (301) 744-4410**

**[hawleyej@ih.navy.mil](mailto:hawleyej@ih.navy.mil)**