

John Day Navigation Lock

Monolith Repair

Presented by Matthew D. Hanson, P.E.

Portland District

August 4, 2005



John Day Navigation Lock **Catastrophic Failure Prevention** **and Monolith Repair**

Presented by Matthew D. Hanson, P.E.

Portland District

August 4, 2005



JOHN DAY DAM



JOHN DAY NAVIGATION LOCK



Historical

- **1968 - Project completed and pool filled.**
- **Post tension anchors installed in navigation lock gate and tainter valve monoliths (5,6,29,30,27,28,7,8,) as a result of problems at Ice Harbor before lock was filled.**
- **Seepage noted at D/S toe of North embankment (right abutment) 5 days into initial filling @ pool .**
- **July 1968 structural inspection cited areas of spalling concrete and water flowing down stair treads in the powerhouse gallery.**

Historical Cont'd

- **March 1969: First Periodic Inspection cited spalling, cracking, inadequate reinforcement**
- **Subsequent reports indicate increasing amount of cracking, spalling, failed waterstops and leaking.**
- **Continuous monitoring and repairs on lock monoliths, concrete, etc.**
- **Waterstop repair contract, tainter valve shaft concrete removal contracts (2001)**

Historical Contd'

- **Primary Problems necessitating repair (2003)**
 - Monolith 8 split in two pieces
 - Monolith 27 in danger of failure
 - Monolith 8 valve shaft spalling and Tainter valve out of service – no operational redundancy
 - Leakage into backfill and boneyard (sinkholes)
 - Monolith movement, cracking, spalling, etc.
 - Customer complaints

Boneyard Sink Hole





Backfill

Monolith 8

Monolith 10

Settlement




Monolith 8 Service Gallery – Tainter Valve Shaft




Monolith 8 Service Gallery Concrete Cracking


John Day Lock Crackmeter 1




Navigation Lock Monolith 8 Tiltmeter Array



John Day Navigation Lock – Confirmed Crack Planes




John Day Navigation Lock – Confirmed Crack Planes



- Crack M27-1 to be repaired using epoxy adhesive grout in typical fashion.
- Crack M27-2 to be repaired using paste-epoxy adhesive for condition similar to Monolith 8 Bulkhead Slot


Monolith 27 El. 263.0 Service Gallery

John Day Navigation Lock – Concrete Rehabilitation



John Day Monolith Repair Contract Investigation

- Stress analysis
- Monolith drilling for crack location
- Instrumentation/monitoring
- Concrete testing
- Finite Element Analysis



John Day Monolith Repair Contract

How/Why did this happen?

- Navigation Lock is not reinforced adequately
- Concrete strength/quality is variable
- Foundation is inconsistent and of questionable quality
- Previous repair measures may have caused cracks which have progressed
- Waterstop failure due to movement of monoliths allows water into monolith

Monolith Repair - Contract

Lift Joint Repair, Monolith 6&8 Crack Repairs



Monolith 8 Structural Repair



Monolith 27 lift joint and Structural Repair



Concrete Removal and Precast Panel Installation



John Day Monolith Repair

Construction issues

- Construction scheduling/considerations of high concern due to lock outage impacts
- Schedule shift due to Anchor testing
- Lock outage in march to be extended to 1 month to perform below tailwater drilling
- 12 hour outages above tailwater after outage
- Best Value contracting method determined in best interest of the Government
- Critical Contract/Last chance for repair

John Day Navigation Lock Monolith 8

•Post Tensioning Design

- Solid A722 150 ksi Anchors were selected for design.
- Anchors were designed to resist the hydrostatic load at $0.6F_y$.
- An additional 40% increase in required number of bars was then allocated.
- In addition, drilling tolerances have been reduced to $\frac{1}{2}$ a degree – or within 4” in a 40’ deep core.
- Tight tolerances will also help prevent hitting existing PT, existing shafts, existing voids, etc.

John Day Navigation Lock Monolith 8

- **Anchor Stressing**

- **Every anchor is proof tested to 150% of the design load ($0.6F_y$).**

- **Several anchors in rock are creep tested to 150% DL for 8 hours.**

- **150% DL is the Corp's single anchor failure criterion. (PTI Criteria 133% DL)**

- **Anchors locked off at $0.6F_u$.**

John Day Navigation Lock Monolith 8/27


- **Anchor Details**


- **Double corrosion protection for anchors installed in rock.**

- **Single corrosion protection for anchors installed in concrete.**

- **Recessed Anchorage zones with tensile zone reinforcement.**

- **Removable anchor caps to allow for retensioning/lift off testing.**





SECTION THROUGH MONOLITH B AT EL. 165.0

SCALE: 1/4" = 1'-0"




John Day Monolith Repair - Construction



John Day Navigation Lock Monolith 27

- **Monolith 27 Post Tensioning Design Cont...:**
 - **New PT was angled and smaller bars were used to eliminate the need to develop bars in the rock strata.**
 - **Fewer monolith penetrations and the no existing PT made the location of these new anchors much less complicated.**
 - **Anchorage details similar to monolith 8 repairs.**



PLAN EL. 250.0


SCALE: $\frac{1}{32}'' = 1'-0''$

John Day Navigation Lock Monolith 27



John Day Navigation Lock Concrete Rehabilitation


- Monolith Joint Isolation/Sealing**
- Concrete Repair Monolith 6**
- Concrete Lift Sealing**
- Crack Sealing/Repair**
- Backfill Drain Rerouting**



Monolith 8/10 Joint Isolation

1. Isolate joint from crack to prevent epoxy grout from bonding joint.
2. Drill two vertical 10-inch dia access shafts.
3. Place expanding chemical “foaming” grout to fill Polyurethane Injection Zone
4. Grout Crack.

John Day Navigation Lock – Concrete Rehabilitation



John Day Monolith Repair Contract Joint Sealing Mock-up Testing



Drilled shaft

Simulated monolith joint

Effectiveness of joint
filler



Monolith Joint - Paste Epoxy Injection




Monolith
joint


Injection
Ports



Post Tension
anchor holes

Epoxy
Injection Ports





Paste-Epoxy Injection

- Paste-Epoxy injection allows a controlled placement due to a predictable and consistent epoxy distribution “bulb.”
- Applicable in a “blind” crack situation

Paste-Epoxy Injection Procedure

1. Stage 1 injection until epoxy is observed at 2nd port above.
2. Stage 2 injection at intermediate ports.

John Day Navigation Lock Monolith Repair Successes

- Structural Integrity restored**
- Normal Lock Operation**
- Leakage to backfill reduced**
- Leakage to lock face reduced**
- Joints/cracks sealed**
- No significant contract claims**

John Day Navigation Lock Monolith Repair Costs

- Original contract estimate \$5.6 million**
- Contract Cost \$11.7 million**

High cost due to

Tight timeframe

Tight Construction Tolerances

Work Within an Operating Lock

John Day Navigation Lock

Portland District
Corps of Engineers



Thanks for
Listening

Questions ?

