

#### Mel Price – Auxiliary Lock Downstream Miter Gate Repair






One Corps Serving the Armed Forces and the Nation



#### Mel Price Locks and Dam





Project Location



**US Army Corps** of Engineers®

#### Mel Price Locks and Dam









## Mel Price Accident 3 October 2004

What Happened?

Why Did It Happen?






#### **Mel Price Accident**

What Happened?



#### Miter Gate Functioning Normally








#### Gate Leafs Forced Downstream From Normal Mitered Position







#### Gate Leafs Forced Downstream From Normal Mitered Position









#### **Mel Price Accident**

## **Damage Summary**



## Damage to Gate Anchorages















## Damage to Gate Anchorages








## Failed Operating Struts









## Diagonal Failure





One Corps Serving the Armed Forces and the Nation



## Damage to Miter End of Leafs

**US Army Corps** of Engineers®












#### Pintle Socket Sheared Off








#### Bent & Cracked Pintle Socket







#### Pintle Ball Retainer Sheared Off







#### Bottom Seal Damaged









#### **Mel Price Accident**

# Why Did It Happen?



US Army Corps of Engineers®

## Gate Operating Arm








US Army Corps of Engineers®

## Operating Arm Failure Tube








#### Failure Tube







#### Normal Miter Block Position








**US Army Corps** of Engineers®

#### **Gate Control Stations**







#### Magnetic Proximity Switch on Gate





One Corps Serving the Armed Forces and the Nation



US Army Corps of Engineers®

## Switches on Machinery Rack





## Modification of PLC Logic

**US Army Corps** of Engineers®






## Miter Gate Sill








## Miter Gate Sill







## Investigation Report Findings



- Increased hydraulic system relief pressures and fracture of the strut failure tube failure bolts.
- Leaves not mitered.
- PLC programming incorrectly indicated that the downstream gate was mitered (closed).
- No operator verification of miter or intervention.
- Filling of lock chamber with the downstream gate leaves not in miter.
- Appreciable unbalanced head on the unmittered downstream gate leaves
- Catastrophic failure miter gate leaves move past miter







## Based on Report Recommendations

- 1. Standard Operator Procedures and Training
- 2. Programming Ladder Logic Control
- 3. Additional Miter Gate Switch
- 4. Policy on Changes and Inter-Office Coordination
- 5. Relief Valve Gages and Mechanical Linkages





## All-Discipline Team





## Concentrate On Critical Activities

US Army Corps of Engineers®







**US Army Corps** of Engineers®



## Variety of Contract Instruments





### Team Visits



Engineers conferring with Contractor

Diagonal Stressing Team





# What We Did Right



- All-Discipline Team
- Communicate, Communicate, Communicate
- Concentrated On Critical Activities
- Hired Contract Employee To Schedule Service Base And Contractor Work
- Contingency Planning
- Used Any and All Contract Options
- Team Project Visits To See Progress
- Kept Exec Office Involved
- Risk reduction measures to keep the main lock operating.






# Gate Repairs






# Gate Repairs


Pulling Gate



### Position of Leafs After Accident







### **Cutting Gate Anchors**







### Removing Illinois Leaf





**Crane "Hercules"** 



### Placing Illinois Leaf on Spare Gate Barge







### Guy Cables Installed







### Guy Cables Installed







### Both Leafs Secured on Spare Gate Barge







# Damage Inspection







### Surveying Damaged Gate








### Survey Results – Illinois Leaf









### What Do We Do Now?





### Panel of Experts

- Retired construction and operations personnel from USACE (Similar Failure At Bankhead)
- Steel structures engineering experts from various universities
- Heat straightening expert
- Structural engineers from other USACE offices
- St. Louis District structural engineers, lock operations personnel and Rivers Project Office personnel





### Conclusions From Panel of Experts

- Gate could be repaired
- Repair would be quicker than replacement
- Heat straightening could be used
- Leafs should be layed down for repairs





# Gate Repairs

# Laying Leafs Down



### Original Lifting Beam For Vertical Lifting Only
















# Lifting Beam In "Green Monster" Test Rack







### Installing Lifting Beam







### Turning Feet for Gate Laydown









### Removing Guy Cables








### Shreve Moving Leaf For Lay Down







US Army Corps of Engineers®

### Aligning Turning Feet on Support Stands








### In Position for Laydown







### Rotation on Turning Feet







# Shreve Setting Leaf Horizontal













# Gate on Support Stands





# US Army Corps Gate Leafs in Horizontal Position







US Army Corps of Engineers®

# Leaf Supported In Deflected Position





US Army Corps of Engineers®



### Enclosure on Delong Barge at Service Base







# Gate Repairs

# Heat Straightening



US Army Corps of Engineers®



# Heat Straightening Crew







# Heat Straightening





# Spot Heats









# Heat Straightening Diagonals







#### Diaphragms Before Heat Straightening





#### Diaphragm After Heat Straightening





One Corps Serving the Armed Forces and the Nation





#### Support Condition For Checking Straightness







### Gate Repairs

# Structural Repairs



# Revised Strut Arms and New Pintle Sockets







#### Machining Strut Arm at Service Base







#### Fabrication Work at Service Base








#### Welding Strut Arm at Service Base









### Modified Bottom End of Diagonal









### Modified Bottom Diagonal Gussets









# Modified Bottom End of Diagonal







#### Castings Supplied By Rock Island Arsenal







# Gate Stops on Miter Gate Sill









# Lifting Repaired Leafs Vertical



# **Installing Lifting Device**







# Shreve Lifting Leaf Vertical







### Shreve Lifting Leaf Vertical









### Placing Leaf In Toaster






# US Army Corps Leafs In Toaster for Transport to Lock of Engineers®









# Reinstalling Gate





#### Repaired Illinois Leaf in Place



One Corps Serving the Armed Forces and the Nation



#### Welding & Boring Gudgeon Pin Plates









#### Welding & Boring Gudgeon Pin Plates







# Installing Missouri Leaf









#### Repaired Gate Leafs in Place







#### Repaired Gate Leafs in Place





#### **US Army Corps**

# of Engineers<sup>®</sup> July 2005 - Auxiliary Lock Back In Service









#### Thank You!!!