

FATIGUE AND FRACTURE ASSESSMENT

JESSE STUART
HIGHWAY BRIDGE

HUNTINGTON DISTRICT


John J. Jaeger, Ph.D., P.E.

(o) 304-399-5254

(c) 304-444-6043

US Army Corps of Engineers

John.J.Jaeger@Lrh01.usace.army.mil




Greenup Bridge



View of Jesse Stuart Highway Bridge looking north (downstream) from Kentucky side of the Ohio River.



JESSE STUART HIGHWAY BRIDGE
 GREENUP LOCKS AND DAM OHIO RIVER
 SEPTEMBER 9, 2003




UPSTREAM ELEVATION

SCALE: 1/4" = 10'-0"

NOTE:
 DIAGONAL HAIRLINE CRACKS IN
 CAP OF LEFT END DAM PIER, US
 WEST SIDE AND US & DS EAST SIDE.

NOTE:
 DIAGONAL HAIRLINE CRACKS
 IN CAP, ALL FOUR SIDES.



FRAMING PLAN - UNIT 1 OR UNIT 3

BOTTOM LONGITUDINAL STIFFENER RETROFIT LOCATION
 TOP LONGITUDINAL STIFFENER RETROFIT LOCATION




Longitudinal stiffener termination, Girder A', Span 11, Unit 3



Crack at the Termination of the Longitudinal Web Stiffeners



Close-up view of cracked longitudinal stiffener termination.



CRACK LOCATION PLAN (SUPERSTRUCTURE 2)

- TYPE 1 CRACK BELOW WEB - FLANGE WELD
 - TYPE 2 CRACK ABOVE STIFFENER - WEB WELD
 - × TESTING INDICATED NO ACTUAL CRACK
 - ⊙ TEST NUMBER
- } SEE DETAIL

JESSE STUART HIGHWAY BRIDGE
GREENUP LOCKS AND DAM OHIO RIVER
 SEPTEMBER 9, 2003



Web gap cracking at inside (upstream) web face
at Cross Frame 1, Span 4 of Girder A, Unit 2.




Web gap cracking at outside (downstream) web face at
Cross Frame 2, Span 4 of Girder A, Unit 2.



Web gap cracking at inside (upstream) face at
Cross Frame 2, Span 4 of Girder A, Unit 2.



Web gap cracking at inside (upstream) face at
Cross Frame 3, Span 4 of Girder A, Unit 2



Web gap cracking at inside (upstream) face at
Cross Frame 3, Span 4 of Girder A, Unit 2.



Web gap cracking at outside (downstream) web face at
Cross Frame 3, Span 4 of Girder A, Unit 2.

General Types of Fatigue Cracking

- Load-Induced
- Distortion-Induced

Load-Induced Fatigue Cracking

- Nominal Stress Range
- Number of Applied Load Cycles
- Connection Details

Load-Induced Fatigue (Type 3 Cracking)

- Longitudinal Stiffener Termination
 - Category E Detail
 - Stress Range $6.3 \text{ ksi} < 13.0 \text{ ksi}$
 - Termination Opposite a Transverse Stiffener

Distortion-induced Fatigue Cracking (Type 1 & 2 Cracking)


- Stress Ranges Complex
- Localized Stresses unintended/Unknown
- Out-of-Plane Distortion



View of typical cross frame in Unit 2.

Distortion-Induced Fatigue

- Transverse Stiffener Connection
 - “Tight Fit (No Weld)”



Typical Cracks in Center Spans

*Note measurements from Periodic Inspections. Blue writing is from FY01. Black writing is from FY03. Top crack grew 5/8" and the lower crack grew 1/8" in a two year period.




View of typical cross frame in Unit 1 (and Unit 3).


Fracture Assessment

- Three Charpy V-Notch impact test specimens were tested from each of Units 2 and 3.
- Unit 2 web specimens averaged energy absorption is 261 ft-lbf.
- Unit 3 web specimens averaged energy absorption is 38 ft-lbf (low value 29 ft-lbf)
- Test temperature 40F corresponding to AASHTO Temperature Zone 2
- AASHTO required minimum energy absorbed value is 25 ft-lbf for ASTM 588 in Temperature Zone II.
- LEFM used to assess Type 3 crack as “thru-thickness in infinite wide plate”.
- Critical crack length is conservatively twice the existing length of 2.25”.

Retrofit for Type 1 and Type 2 Cracks.




HOLE DETAIL
TYPE 1 AND TYPE 2 CRACKS
WITH CRACK FOLLOWING TOE
OF WELD




**TOP FLANGE WELD
TERMINATION DETAIL**


LEGEND:

 = AREA TO BE
SANDBLASTED

Retrofit for Type 3 Crack



PLAN




ELEVATION

RETROFIT TYPE L2
LONGITUDINAL STIFFENER RETROFIT
WITHOUT TRANSVERSE STIFFENER ON
OPPOSITE SIDE


Summary

- 42 fatigue cracks exist as of September 2003
- Probable cause is load-induced and distortion-induced fatigue cracking
- Limited material testing indicates adequate fracture toughness for webs
- Observed Type 1, 2, & 3 cracking does not impose an immediate structural threat.
- Existing web gap cracking does not reduce load-carrying capacity of girders.
- Permitted loads will be assessed and limited where possible.

Discussion!



PLAN



ELEVATION

✦ FILL WITH CAULK PRIOR TO PRIMING AND PAINTING. CAULK SHALL BE A TWO-COMPONENT, NON-SAG, NON-SHRINK 100 PERCENT SOLIDS EPOXY CAPABLE OF FILLING VOIDS UP TO 1/2 INCH.

RETROFIT TYPE LI

LONGITUDINAL STIFFENER RETROFIT WITH TRANSVERSE STIFFENER ON OPPOSITE SIDE