

*Presentation  
to the*

***2005 Tri-Service Infrastructure  
Systems Conference  
Geotechnical Community of Practice***

***Grout Curtains at Arkabutla Dam  
Outlet Monolith Joints and Cracks  
using Chemical Grout,  
Arkabutla Lake, MS***

*by*

***Dale A. Goss, P.E.***

***Mississippi Valley Division***


***Regional Technical Specialist - Concrete and Materials Engineer***

***August 3, 2005***



US Army Corps  
of Engineers®

# Mississippi Valley Division



One Corps Serving the Armed Forces and the Nation



US Army Corps  
of Engineers®

# Vicksburg District




**Arkabutla  
Lake**

*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

# ARKABUTLA LAKE OUTLET WORKS



— *One Corps Serving the Armed Forces and the Nation* —



**US Army Corps  
of Engineers®**



# **BACKGROUND**

- **Condition of Conduit**
- **Previous Grouting**
- **Previous Joint Repair**

---

*One Corps Serving the Armed Forces and the Nation*

---







**US Army Corps  
of Engineers®**

# Table 1



Previous Grouting at Outlet Works Performed during 1950 and 2003								
Joint No.	Cement Grout, Cu. Ft.			Chemical Grout, gal.				Cement Grout, Cu. Ft.
	1950	1971	1977	1988	1998	2000	2003	2003
Transiiton/1								
1/2		0.5	0.4	3.5	2.5	5.0	15	11.4
2/3	1.0	0.6		15.0				10.0
3/4	9.5	410	0.5	2.0				
4/5	12.5	4.6			13.4			
5/6	47	33.1	6.9	9.0				
6/7	98	67.6	7.6	10.0				
7/8	7	0.8						
8/9		0.6	1.0					
9/10		1.0						
10/11		0.6						
11/12		0.4						
12/13								
Subtotal	175	519.8	16.4	39.5 <sup>1</sup>	2.5 <sup>2</sup>	5.0 <sup>2</sup>	15 <sup>2</sup>	34.8
	711.2			62 gal. ≈ 285.8cu. ft				
Total	1031.8 cu. ft. (38.2 cu. yd.)							

Note: 1. The chemical grouting was performed using Hydro Active Cut ( 1 gal ≈ 6.67 cu. ft. of stabilized soil)  
 2. The chemical grouting was performed using Hydro Active Flex LV (1 gal ≈ 1 cu. ft. of grout)  
 3. Settlement of monoliths 1 through 8 of approximately 11 inches account for the loss of 78 cu. yd. of material.

*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

## Sand Bags, Three foot high, to Control Sand Boil at Monolith Joint 5/6, Aug. 2003



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

## 3/4 Cubic Yards of Foundation Sand piped through Monolith Joint 5/6, Aug. 2003




*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

# OUTLET WORKS

## Constructed in 1941



One Corps Serving the Armed Forces and the Nation



US Army Corps  
of Engineers®




# Installation of Stainless Steel Plates at Two Monolith Joints as Test Section

— *One Corps Serving the Armed Forces and the Nation* —



US Army Corps  
of Engineers®

## Detail for Installation of Stainless Steel Plates at Monolith Joints 5/6 and 6/7, Aug 2004



One Corps Serving the Armed Forces and the Nation



US Army Corps  
of Engineers®

## Forming Plug at Concrete Surface of Conduit for Injection of Chemical Grout between Waterstop and Plate.



— One Corps Serving the Armed Forces and the Nation —



US Army Corps  
of Engineers®

## **Geotextile and Rubber Strips placed between Concrete Surface and Plate to trap any Material that could pipe through joint.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

## Completed Plate Installation at one of the Monolith Joints, 17 Aug. 2004



— *One Corps Serving the Armed Forces and the Nation* —



US Army Corps  
of Engineers®

## Failure of Plate at Monolith Joint 5/6 a Few Weeks after Installation, 2 Sep. 2004



— *One Corps Serving the Armed Forces and the Nation* —



US Army Corps  
of Engineers®

## Close up View of Stainless Steel Plate Showing Tearing and Bending of Plate, 2 Sep 2004




— *One Corps Serving the Armed Forces and the Nation* —



US Army Corps  
of Engineers®

**Example of 1/4-inch diameter jets of water  
observed on 26 Jan 05 from one location Joint  
2/3 and from 3 locations Joint 3/4**



*One Corps Serving the Armed Forces and the Nation*




US Army Corps  
of Engineers®

# Location of grout holes



Approximate location of the 9 holes using odd numbers, 9 through 17 or 1 through 9 depending on either looking upstream or downstream, respectively. Even number holes were used to verify soil stabilization between primary injection holes.




One Corps Serving the Armed Forces and the Nation



US Army Corps  
of Engineers®

# Theoretical Cross Section of Stabilized Soil (Grout Curtain)



Assuming that grout is injected at the bottom of the conduit and expands radially from the injection point. For example if 2.7 gallons were injected at a hole, the radius of the hemisphere created would be 24.5 inches.

Assuming 0.15 cu. ft. voids/ cu. ft. of soil, and 1 gal of liquid chemical grout  $\approx$  1 cu. ft. of urethane foam. Therefore, volume of sand stabilized =  $1/0.15 = 6.67$  cu. ft

Chemical grout being injected as a hemisphere, radius =  $\sqrt[3]{(3V/2\pi)}$ ;  
 $V = 2.7$  gal (6.67 cu. ft./ gal)

$$\sqrt[3]{[(3)(18.0)/2\pi]} = 2.05 \text{ ft} = \mathbf{24.5 \text{ inches}}$$



US Army Corps  
of Engineers®

# Table 2



Hole No.	Monolith Joints or Cracks, 14-23 February 2005																Remedial Effort	
	T/1	1/2	2/3	A(3)	3/4	4/5	5/6	B(6)	6/7	7/8	8/9	9/10	10/11	11/12	12/13	13/C	A(3)	C(5)
Chemical Grout Take per hole (gallons)																		
1	0.7	6.5	8.0	4.0	2.7	0.5	1.8	1.5	0.9	3.5	3.5	0.7	0.5	0.5	0.7	18"		3
2		0.5				G	G		G			0.5		G	G			
3	0.5	G	8.5	4.0	9.0	1.5	3.6	4.5	0.5	0.5	3.5	3.6	2.5	1.5	0.5	18"		0.5
4	G	6.3				6.7	0.9		3.5									
5	0.5	2.7	5.5	4.0	3.6	0.9	8.5	4.5	1.5	3.5	3.0	3.0	3.5	5.4	4.5	steel		5
6		4.5				8.5											5.0	
7	5.8	0.5	4.5	4.0	1.5	0.9	0.5	3.5	8.5	4.5	3.5	2.6	4.5	1.5	4.5	steel		1.5
8			1.0			G	9.0										5.0	
9	8.0	8.0	2.5	4.0	4.5	4.0	1.9	3.0	0.5	3.0	3.5	3.0	0.5	4.5	5.4	13.5		3.0
10					G								2.5				5.0	
11	1.0	4.5	9.0	4.0	4.0	6.7	0.5	0.9	6.0	4.5	3.5	2.6	0.5	2.5	4.5	steel		5.0
12	0.5						7.0						2.5					
13	0.5	4.3	2.5	4.0	0.5	9.0	2.5	3.5	2.5	3.0	3.5	2.6	4.0	0.5	4.9	steel		3.0
14	G				9.0						0.5		0.5					
15	0.5	4.5	13.0	4.0	1.5	0.5	1.9	0.5	2.5	3.5	0.5	0.5	0.5	0.5	4.5	18"		5.0
16	G	2.5			G	0.2		G	G		G	0.5	0.5	G	G			0.00
17	0.5	1.4	1.0	4.0	0.5	1.5	4.0	0.5	0.9	3.5	0.9	1.4	0.9	0.5	0.5	18"		0.25
18						3.6												
Total	18.5	46.2	55.5	36.0	36.8	44.5	42.1	22.4	27.3	29.5	25.9	21.0	23.4	17.4	30.0	13.5	15.0	26.25
490.0 gallons ≈ 3267 cu. ft of stabilized sands																41.25 ≈ 275		


Notes: T – Transition Monolith; C- Chute Monolith; A(3) is crack in monolith 3; B(6) is crack in monolith 6; C(5) is crack in monolith 5;  
G – drilled hole at this location and chemical grout was found and no additional chemical grout could be injected.



US Army Corps  
of Engineers®

# OUTLET WORKS

## Constructed in 1941



One Corps Serving the Armed Forces and the Nation



US Army Corps  
of Engineers®

**Drilling of Holes during Feb 2005. Water used  
to remove cuttings from holes otherwise bit  
would become locked in hole.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

**Washing injection tubing into drilled hole.  
TopCor Services, Baton Rouge, LA, personnel  
performed the chemical grouting.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

## Placing oakum saturated with chemical grouting in annular space around tubing using a screw driver to pack the oakum



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

**Line for injection of chemical grout beneath  
conduit is attached and grout is being  
injected. Notice light brown color of material  
above tubing is water and unset liquid grout.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

**Chemical grouting has setup after sealing off any voids in a joint or crack large enough to allow water seepage (0.02 in width).**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

**Foundation sand being pumped at monolith joint T/1 by gases being released from chemical grout injected at monolith joint 2/3, 50 feet away, prior to grouting joint T/1.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

**Chemical grout has been measured in gallon bucket and catalyst was added and mixed by hand. Pouring grout into bucket so that it can be injected.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

# Pails of Hydro Active Grout used for sealing joints and cracks and to bind foundation sands together beneath the conduit




— One Corps Serving the Armed Forces and the Nation —



US Army Corps  
of Engineers®

## Can of Hydro Active Cut Catalyst used to vary setting time of chemical grout.



One Corps Serving the Armed Forces and the Nation



US Army Corps  
of Engineers®

**Drilling holes at cracks in monoliths 3 & 5 during  
June 2005. Holes drilled at an angle of 45 to 60  
degrees to surface to intercept cracks.**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®



**Crack in monolith 5, the grout migrated up the crack to approx. 9 o'clock and then traveled through a zone of honeycombed concrete. Exited 7 feet downstream of crack**




*One Corps Serving the Armed Forces and the Nation*




US Army Corps  
of Engineers®

# Monolith joint 4/5 showing weeping from construction joint on left side of conduit when looking downstream, 24 Feb 05




— One Corps Serving the Armed Forces and the Nation —



US Army Corps  
of Engineers®

# Monolith joint 4/5 showing weeping from around grout nipple on right side of conduit when looking downstream, 24 Feb 05




— One Corps Serving the Armed Forces and the Nation —



US Army Corps  
of Engineers®

**Crack in monolith 5 which was not grouted.  
Seepage at 2 feet left of centerline when looking  
downstream, 24 Feb 05**



*One Corps Serving the Armed Forces and the Nation*



US Army Corps  
of Engineers®

## Monolith joint 13/C showing a good seal due to the chemical grouting



— One Corps Serving the Armed Forces and the Nation —



**US Army Corps  
of Engineers®**

# Table 3



Monolith Joints or Cracks	Remarks
Visual Evaluation of Chemical Grouting on 24 February 2005, Day after Completing the Initial Grouting	
T-1	Minor weeping at construction joint, right side
1/2	Minor weeping at construction joint and at grout nipple right side
2/3	Minor weeping at grout nipple, left side and construction joint right side
A(3)	Seepage 1 foot left and 2 foot right of center. Also, bubbles escaping indicating chemical grout still active.
3/4	Minor weeping at grout nipple right side
4/5	Minor weeping at grout nipple, right side, and at construction joint, left side
Crack Monolith 5	Not grouted, Seepage 2 feet left of centerline and 2 feet right of centerline. Flow increased to 1 gallon per minute from the invert on 21 Mar 05.
5/6	Seepage 3 feet left of centerline
B(6)	Seepage 2 feet left of centerline
6/7	Minor weeping at construction joint right side
7/8	Good
8/9	Minor weeping 4 feet right of centerline
9/10	Minor weeping 2 feet left of centerline
10/11	Minor weeping 2 feet above grout nipple on right side
11/12	Good, damp but not weeping
12/13	Good, damp but not weeping
13/C	Good
NOTES: Damp – Concrete surface is darker than surrounding area but when area is touched, fingers remain dry. Weeping – Concrete Surface is dark and reflective and when touched, fingers will be damp. Seepage – Visually can see water movement on concrete surface.	



**US Army Corps  
of Engineers®**

# Table 4




Monolith Joints or Cracks	Remarks
Visual Evaluation of Chemical Grouting on 9 June 05, Day after Completing Remedial Grouting.	
T-1	Damp at construction joint, right side
1/2	Damp at construction joint and at grout nipple right side
2/3	Damp at grout nipple, left side and construction joint right side
A(3)	Good, bubbles escaping indicating chemical grout still active.
3/4	Damp at grout nipple right side
4/5	Damp at grout nipple, right side, and at construction joint, left side
C(5)	Good, bubbles escaping indicating chemical grout still active.
5/6	Damp 3 feet left of centerline
B(6)	Minor weeping from crack at 2 o'clock and 10 o'clock
6/7	Damp at construction joint right side
7/8	Good
8/9	Good
9/10	Good
10/11	Good
11/12	Good
12/13	Good
13/C	Good
<p>NOTES:            Damp – Concrete surface is darker than surrounding area but when area is touched, fingers remain dry.            Weeping – Concrete Surface is dark and reflective and when touched, fingers will be damp.            Seepage – Visually can see water movement on concrete surface.</p>	



US Army Corps  
of Engineers®



# QUESTIONS?



————— *One Corps Serving the Armed Forces and the Nation* —————



**US Army Corps  
of Engineers®**



**Dale A. Goss, P.E.**

**Mississippi Valley Division**

**Regional Technical Specialist – Concrete and Materials Engineer**

**US Army Corps of Engineers, Vicksburg**

**4155 East Clay Street (ED-GI)**

**Vicksburg, MS 39183-3435**

**Phone: 601-631-5640**

**E-mail: [Dale.A.Goss@us.army.mil](mailto:Dale.A.Goss@us.army.mil)**

*One Corps Serving the Armed Forces and the Nation*



**US Army Corps  
of Engineers®**



- **TopCor Services, Baton Rouge, LA**
  - **Jon Gary – Project Manager**
  - **Stephanie Duplanits “Zena” – Crew Chief**
  - **Van Taylor – Crew Chief**
- **Arkabutla Lake Project Personnel**
- **MVK HQ – ED-D, ED-G, ED-O, ED-P, ED, C & Project Delivery Team**
- **Greenwood Area Office**
- **Inspectors – Noah Vroman, Jay Sims, & Al Hitchcock**