



# Ruptured Case in the M249 SAW

A Finite Element Analysis

# [ Who am I? ]

---

Clinton Fischer

Weapons Systems and Technology  
Weapons Technology Branch

RDECOM-ARDEC

Picatinny Arsenal, NJ 07806-5000

# [ Introduction ]

---

- Modeling and Simulation saves time and money
- Impractical to do real world tests on some failures

# [ What Happened ]



- Incidences of the M855 cartridge case rupturing during normal firing of the M249 Saw
- Cause was unable to be determined during live fire

# [ What Do We Need to Know ]

- Do the tolerances of the cartridge case need to be more stringent?
- If so, which tolerances are causing the problem; and how much do they need to be changed?

# [ What Can Contribute ]

---


- Separate Tolerances
- Tolerance Stack-Up
- Hardness Gradient

# [ Setup ]

---

- Geometry
- Internal Pressure from Propellant
- Extraction taken from T-D Curve
- Materials – Brass Hardness Gradient


# [ Preliminary Modeling ]



- Axi-symmetric Model
- Several scenarios were considered




# Observations



- No rupture in nominal case
- Longitudinal stretching causes rupturing
- All hardness gradients ruptured at same location and time

# Secondary Results



- 3d Results corresponded to axi-symmetric models
- Brass material validated to 0.08% error

# [ Conclusions ]

---

- Space between the back of the case and the Bolt Face causes case rupturing
- Weapon head space is measured, case tolerance is limited to -0.006in
- Head space gauges measured in 0.002in increments

# [ What can be Learned ]

---

- Most cartridge cases are generally the same shape so will behave approximately the same way