



Multi-Option Fuze for Navy (Mk 437 MOFN)

51st NDIA Fuze Conference

May 22-24, 2007

Mr. Brian Will

Naval Surface Warfare Center, Dahlgren Division, Fuze Branch - Code G34

brian.will@navy.mil

(540) 653-5481 DSN: 249-5481


Fuze Navalization



➤ “Navalize” the Army M782 Multi-Option Fuze for Artillery (**MOFA**) for use with the US Navy 5” Gun Weapon System

➤ Provide a moderately priced Multi-Mode of Operation Fuze for Naval Surface Fire Support & Surface Warfare Missions

Army




Navy



Navalization Approach

Retain **MOFA** Functional Modes:
Mk 437 MOFN = M782 MOFA

Surface Proximity (HOB)




Electronic Time (ET)



Note: Navy will use
ET Mode vs. HSMST

Point Detonating Delay
(DLY)



Point Detonating (PD)




Navalization Considerations



Gun weapon system & mission changes

- ◆ PIAFS* \Rightarrow MK 34 Fuze Setter
- ◆ EMV: More Radiation to Deal with
- ◆ Safety & Qual Requirements different
- ◆ Different mission: close-in speed boats

Army




Navy



*PIAFS = Portable Inductive Artillery Fuze Setter

Overview of Changes


Summary of Engineering Changes (none went as planned)




- Changes To Inductive Interface Hardware
- Unexpected Electronics EMV Hardening
- Changes To Fuze Software
(Unexpected Complete Software re-write)
- Unexpected Improvement to fuze seals
- Changes To Safe & Arm Device Explored
(Unmodified S&A determined to be sufficient after much mechanical design, test & safety analyses)

Required Engineering

Inductive Interface Changes




Initial Engineering Design Approach up to PDR:



- Bobbin made of Magnetic Material
- ~ twice the number of windings
 - smaller gauge
- Magnetic Material could not be manufactured

Final Engineering Design Approach:




- Same bobbin as **MOFA**
- Same # coil windings
- Added Magnetic Core

Required Engineering

Inductive Interface Changes (cont.)

Final Engineering Design Approach:

➤ Minor Changes to Electronics:



➤ Changed inductive tuning components

➤ New Flex Card Layout

➤ Changes to Pin assignments

➤ Different Voltage Detector



Required Engineering

Software Development

- Complete re-write of **MOFA** software
- Object Oriented Design
- 95% High-level language (5% assembly code)
- Development based on IEEE/EIA 12207.1 &.2
- Hardware in the loop prototype & Qualification testing (G34 & EDC)
- Performed Independent Software Safety Analysis (EG&G)


Required Engineering

S&A changes explored



Standard **MOFA**
Rotor

MOFN Rotor:
3 holes drilled



Standard **MOFA**
Pallet

MOFN Double
Thick Pallet

- Achieve > 420 ft Min Arming Dist. (AVG - 3σ)
- Reliability Gunfire Test resulted in 19/22 successful

Required Engineering

S&A changes explored

- Reliability issues with extended arming distance
- Safe Separation Analysis indicates that unmodified **MOFA** S&A will satisfy safety requirement
- **MOFN** S&A Modification abandoned
 - ◆ Unmodified **MOFA** S&A will be used on **MOFN**



Use Unmodified
MOFA S&A

Schedule

- PDR (Nov 2004)
- Lot A Test (20 Gunfired – Jan 2006)
- Lot B Test (349 fuzes – July 2006)
- Lot C Test (50 fuzes – Aug 2007)
- Award LRIP (Oct 2007)
- At-Sea Shipboard test (June 2008)


➤ Test Results

- ◆ ET met specification
- ◆ HOB over water did not meet specification
 - ❖ 8/15 functioned below the minimum HOB
 - ❖ Bi-modal HOB ~5' & ~40'
- ◆ Gross Leak Testing results did not meet specification

Investigated failures, made fixes, built Lot B

MOFN Lot A Results

Bi-modal HOB over water Heights of Burst



Lot A Bi-modal HOB Issue

- Root Cause Investigation Performed
 - ◆ Root Cause Panel consisted of representatives from Navy, Army, KDI and EDC
 - ◆ 24 Potential Root Causes were identified
- Over land tests did not show same bi-modal response
- Army has never seen bi-modal response in MOFA testing
- Lot B testing did not show bi-modal response
- Phenomena remains unexplained

➤ Test Results


- ◆ MIL-STD-331 tests
 - ❖ Gross Leaks
- ◆ Ballistic Tests in ET, PD, & HOB modes
 - ❖ Duds
 - ❖ Prox failures (PD instead of HOB & no TM)
- ◆ Passed E3 testing

Investigated failures, renegotiated contract, continuing investigation prior to building next lot

Lot B - Leaks

➤ 10% Fail Gross Leak Test

MOFN Seal Locations with # Occurrences of Leaking During Lot B Qual Build Leak Tests



Lot B - Leaks

Radome to Collar O-Seal Damage



O-Seal


Collar Cut completely through to reveal O-Seal without disturbing it.



Inspection shows that O-Seal was Damaged in installation process

Lot B - Duds


- Change to method of sealing Booster cup lead to failures.
 - Lot A – RTV applied to top threads and was blown out by pressure as booster screwed in.
 - Lot B – RTV applied to bottom to prevent this.
- Too much RTV squeezed into S&A and seized S&A creating a dud.



As Lot B Booster cup is screwed in- Excess RTV is forced up into the S&A




RTV on S&A Gears



Lot B – Prox failures

- Failure analysis conducted by KDI
 - ◆ Ferrite Core possibly cutting Transceiver Flex Circuit during gun launch
 - ◆ Spin drop tests to test this possibility
 - ◆ 2 of 10 had cut circuits
- Solutions: Key ferrite core to prevent rotation




MOFN Lot B - Prox Failures


Flex Circuit

Flat on Ferrite Core

**Flat on Ferrite Core
is supposed to
face Flex Circuit**




MOFN Lot B - PROX Failures



MOFN *Planned* Procurements

(No guarantees)



➤ Conclusion

- ◆ Mk 437 MOFN is on track to meeting the Navy's requirements for an affordable multi-mission fuze this FY

For Further information:

Mr. Brian Will

Naval Surface Warfare Center

Dahlgren Division, Fuze Branch - Code G34

(540) 653-5481 DSN: 249-5481