# Product Manager Large Caliber Ammunition


Training Ammunition Safety Initiatives



LTC Kenneth Robertson Project Manager

20 May 2010







## **Agenda**



- Problem
- Cause & Effect
- Technical Solutions
  - -Advanced Case System
  - -Skive Joint Modification
  - -M14 Propellant Replacement
  - Loader Tray Upgrade (discussion)
- Path Forward



#### **Problem**




# Three Incidents of Training Cartridge Ignition Resulting in Fatalities or Injury



#### **Cause & Effect**



- Ignition Caused by a "Perfect Storm" of Events
  - -Cartridge Case Damage
    Caused by Extraction of
    Non-Fired Round from 2<sup>nd</sup>
    Gen Loaders Tray
  - Damage is not FacingLoader–Damage GoesUnnoticed






### **Cause & Effect**



- Chip in the Ready Rack Coating Previously <u>Exists</u>
- Diethyl Ether Fumes Escape from Just Right Sized Hole
- Round Placed in Ready Rack Causing Static Charge-Then Removed for Firing
- Venting Ether is Ignited Due to Electro Static Discharge





# Cause & Effect








## **Advanced Case System**



 ACS Program Eliminates the Bond Joint at Projectile Forward End of Cartridge







## **Skive Joint Modification**




Large Stockpiles of M865,
 M831A1 and M1002 Training
 Cartridges with Forward Skive
 Joint



**Polyurethane Tape** 

ACS Cannot be Applied to M831A1/M1002 in Inventory



Polypropylene Band Edges Sealed with epoxy



## **M14 Propellant Solution**



- Potentially Replace M14 Propellant with Less Vulnerable Solution
- Competitive Contracts with Promising Results
- Reduction in R&D Overall Risk-Leverage Previous Efforts
- Affordability is an Exit Criterion



## **Path Forward**



- •FY11: Skive Joint Modification to Existing Stockpile
- •FY11: ACS Solution to Future Production of M1002/M865

•FY14: M14 Replacement Based Decision by USMC / Army



