



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Bluestone Dam DSA Anchor Challenges

Tri-Service Infrastructure Systems Conference

Michael McCray, P.G.
(304) 399-5234





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Topics


- ◆ **Brief Overview of Bluestone Dam**
- ◆ **DSA efforts completed to date / ongoing and future efforts**
- ◆ **Lessons learned from the field anchor study**



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Location





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team


Features

- ◆ **Concrete gravity dam**
 - 165' high
 - 2060' long
- ◆ **4600 mi² drainage area**
- ◆ **Outlet works**
 - 16 sluices
 - Gated spillway (21)
- ◆ **6 penstocks**



Construction

- ◆ Started in 1942
- ◆ Suspended in 1944 (WWII)
- ◆ Resumed in 1946
- ◆ Completed in 1948
- ◆ Hydropower not implemented
 - Storage re-allocated for flood control
 - Pool elevation reduced from 1490 feet to 1410 feet





Bluestone Dam Overview



Spillway 790' long





Bluestone Dam Overview


◆ Project foundation:

● Valley floor:

- Founded on orthoquartzite or interbedded orthoquartzite and carbonaceous shale


● Abutments:

- Shales
- Siltstone
- Sandstone



DSA Project History

Fault was not removed from monoliths
10 through 12




TOP OF EXISTING DAM - EL 1535

FLOOD CONTROL POOL - EL 1520

POOL OF RECORD - EL 1506

SEASONAL POOL - EL 1410





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Bluestone DSA Phase 1

◆ Phase I Contract


- Awarded Sept. 2000
- Completed 2004

◆ Project Features

- 2 Lane Bridge
- Thrust Blocks
- Extending Penstocks
- Sacrificial Bulkheads



Bridge



Penstocks

Thrust block








Bluestone DSA – Phase 2A

Crest gate
guide
extensions

Route 20 gate
closure

monolith
(not shown)



Upgrade access
road to stilling
basin

Bluestone DSA – Phase 2B

- ◆ Awarded 31 May 2005
- ◆ Brayman Construction Corporation
- ◆ \$30,000,000




Bluestone DSA – Phase 2B

Anchor nonoverflow



**Complete
thrust block**

Bluestone DSA – Phase 2C





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Lessons Learned from the Field Anchor Study

- ◆ **Corrosion Protection**
- ◆ **Drill Hole Alignment**



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

2002 Field Anchor Study

- ◆ **Install Four 61 Strand Production Anchors**
 - Two from top of dam and instrumented (8°)
 - Two from face of dam (45°)
 - Corrosion protection is 10" corrugated polyethylene pipe 70-mil.
 - Bond zones forty feet.
 - Stressed lengths 130 to 200 feet.



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Field Anchor Study (cont.)

◆ Install Eight Bond Stress Test Anchors

- 18 strand anchors in 5" holes
- Bond zones 10'
- Load to, or near, bond failure
- 4 lithologies tested
- Parallel lab pull-out tests for comparison



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Lessons Learned from the Field Anchor Study

◆ Corrosion Protection

- Corrugated

- Thickness
- Handling


- Sheathing

- Polyethylene VS Polypropylene
- Handling

Corrosion Protection

◆ Corrugated (Prinsco, Goldline)

- 70-mil (measured at the crown)
 - 84-mil max
 - 56-mil minimum
- 550 ft lengths





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection

Corrugated collapses

- First lift 9 ft
- Second lift 30 ft
 - Collapses at 9 ft and travels up 8 ft
- All lifts reduced to 20 ft





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Smooth Walled HDPE 1/2" Thick





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

HDPE Welded





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection



Corrosion Protection

◆ Corrugated (Prinsco, Goldline)

- 4-mm (157-mil)
 - Manufactured in maximum 60 ft sections

◆ Smooth Wall (CPChem, Driscoplex 4100)

- 0.5 inch





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection

◆ Smooth Wall Collapse

- First lift 10 ft
- Second lift 41 ft
- Third lift 119 ft (to the surface)
 - Collapse at 51.5 ft



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection

- ◆ **Critical buckling pressure for 10” diameter, 70-mil corrugated: 19 PSI**
- ◆ **Critical buckling pressure for 10” diameter, 157-mil corrugated: 59 PSI**
- ◆ **Critical buckling pressure for 10” diameter, 0.50-inch smooth: 19 PSI**



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection

Specifications call for a 100-mil corrugated

- ◆ **Critical buckling pressure for 10” diameter, 100-mil corrugated: 39 PSI**



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Installation of Corrugated





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Installation of Corrugated

Specifications call for a simple falling head test on the installed, but ungrouted corrugated.

Loss of less than 2.75 gallons in 10 minutes at 5 psi head shall constitute a watertight encapsulation.



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection



**Field Fix of
Polyethylene**







US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Tendon Installation





**US Army Corps
of Engineers**
Huntington District

One Corps, One Regiment, One Team







US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Corrosion Protection

Specifications call for a polypropylene hot-melt extruded coating. Polypropylene is much tougher than polyethylene sheathing but does cost more.



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Alignment Tolerance Field Anchor Study

The scope specified a minimum drill tolerance of 1 in 150. Each drilled hole was surveyed for positional accuracy by the Baker-Hughes INTEQ using the Seeker™ Surveying System.

Survey accuracy

1 in 700 8-degree holes

1 in 300 45-degree holes



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Starter Guide



Sub-Bearing Plate and Trumpet





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Installation and Alignment





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Installation and Alignment



8. 22. 2002



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Installation and Alignment





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

15" Hammer





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Alignment Tolerances


◆ Crest Anchors

- 1 in 110 feet


◆ Anchors on downstream slope

- 1 in 20 feet

Up-Down Deviation from Intended Location Due to Drift



Left-Right Deviation from Intended Location Due to Setup Error





US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Alignment Tolerances

Each bidder was given a video documenting the lessons learned from the 2002 field anchor study and a copy of a report on directional drilling and bore hole alignment measurement technology.



US Army Corps
of Engineers
Huntington District

One Corps, One Regiment, One Team

Alignment Tolerances

Specifications call for each anchor hole to be surveyed using a rate gyrocompass, or equal equipment. If the hole alignment is not within these tolerances, the hole shall be backfilled and redrilled at the contractor's expense.



**US Army Corps
of Engineers**
Huntington District

One Corps, One Regiment, One Team

Questions?

Michael McCray

Phone (304) 399-5234


E-mail mikem@mail.orh.usace.army.mil

Foundation Conditions

◆ Construction Events


Fault was only partially removed from monoliths 13 and 14

* Fault was not removed from monoliths 10 through 12



DSA Project History

Fault was not removed from monoliths
10 through 12



Up-Down Deviation from Intended Location Due to Setup Error

